LOG OF MEETING

DIRECTORATE FOR ENGINEERING SCIENCES

Meeting of the Infant Bedding & Related Accessories Section of the ASTM Juvenile Products Subcommittee SUBJECT:

PLACE: ASTM Headquarters Philadelphia, PA DATE OF MEETING: October 4, 1994

LOG ENTRY SOURCE: John Preston, ESME

COMMISSION ATTENDEES: John Preston, ESME

NON-COMMISSION ATTENDEES:

Richard Glover, Cosco Perry McGlothan, Century Gary Christman, Evenflo David Campbell, Fisher-Price Jack Walsh, Danny Foundation George Kiefer, Owen Mfg. David Seelenfreund, Quiltex Co. Al Kozak, ACTS Testing Labs. Bill Suvak, Child Craft Deborah Fine, The Baby's Room Jeff Lipko, Inchcape Testing Art Kazianis, Hasbro Eric Tarnow, Child's TV W'kshop Cathy Runden, Lambs & Ivy Paula Merkowitz, PatchKraft Nanci Freeman, Red Calliope Bob Waller, JPMA

Bob Craig, B & R Consulting Cecil Cantey, Nelson Kitty Pilarz, Fisher-Price Werner Frietag, Consumer Mary Ellen Fise, Consumer Al Kaplan, Triboro Quilt Rick Harris, Judi's Originals Bill Dean, Riegel/Mt. Vernon Marcie Ridenour, Temple Univ. Keith Moehring, Simmons John Kearney, Hasbro Owen Jones, J.C. Penney Pat Sumergrade, Sumersault Mary Kay Pompetti, Consumer David Sinquefield, Dundee Mills Clare Murnane, JPMA

SUMMARY OF MEETING:

The meeting began with discussion on the provisions in a second draft of a standard for infant bedding and related accessories that had been distributed with the minutes of the

In the General Requirements section, the title of paragraph last meeting. 5.1 was changed from "Strings" to "Bumper Guards." A proposal to increase the length of bumper guard ties from 7 inches to 12 inches was rejected. The last sentence in 5.1 was changed to state: "Bumper guards must have a minimum of six ties and the bumper guard must be secured at or near the corners and in the mid-point of the long sides." A new provision was added requiring bumper guards for circular cribs to have ties spaced at intervals no greater than 26 inches.

In response to a suggestion submitted by a manufacturer, paragraph 6.4, addressing vinyl covering materials a motion was approved to change the requirement to state: "Unsupported vinyl

No Mirs/Prvilbirs or 20 Products Identified Excepted by___ Same and Same

shall not be less than 0.011 in. (0.28 mm) thick when measured in accordance with Section 7.5." The change makes the requirement consistent with a similar requirement in the non-full-size crib standard.

In a discussion of warning labels, a change was approved to the warning required on bumper guards. The new warning will state:

WARNING

To prevent entanglement or strangulation, position ties securely to outside of crib.

When child is able to pull up to standing position, set mattress in lowest position and remove bumper pads, large toys and other objects that could serve as steps for climbing out.

After discussion on the merits of continuing to manufacture infant pillows, a warning suggested by CPSC staff was accepted. This will state:

To prevent suffocation, do not put pillow in any product or near any area where an infant may sleep.

Pillows are a decorator item only and are not intended to be used for an infant to sleep on or to be

For window treatments containing cords or ties greater than 7 inches in length, the following warning will be required:

To prevent strangulation, keep cords and ties out of child's reach.

The warning on diaper stackers was revised to state:

To prevent serious injury, never place on or attach to a crib and keep out of child's reach.

A motion was approved to send the second draft of the standard, as amended at this meeting, to the Juvenile Products Subcommittee for letter ballot.

DISTRIBUTION:

os (2)

ES

EXHR

File